## ACKNOWLEDGEMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573

Assigned Recall No. <u>03V-032</u> by the National Highway Traffic Safety Administration

Part 573 Report Date: January 27, 2003

Date Faxed: February 6, 2003

MANUFACTURER: BMW Group

MANUFACTURER CONTACT:

Mr. Karl-Heinz Ziwica, General Manager,

Environmental Engineering

FAX: 201-782-0764

2435

SUBJECT: 2,520 RMW 2002 X5 and 2003 Z4 model vehicles manufactured from June 20, through September 4, 2002. The connection of the safety belt buckle to the steel rope of the tension does not meet BMW specifications. In severe frontal crashes, this connection can detach.

This is an acknowledgment for this recall. A formal acknowledgment letter will be written if we have additional comments or concerns.

I have reviewed your draft owner notification letter and it meets the requirements of Part 577. However, please change the lessor paragraph on the 2<sup>nd</sup> page to read: "If you are a lessor of this vehicle, Federal regulations require you to forward this notice to your lessee." Thanks.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during February 2003. Therefore, the first quarterly report will be due by April 30, 2003.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or

George Person, Chief on (202) 366-5210 or Fax at (202) 366-7882

or e-mail at pwallace@nbtsa.dot.gov Recall Management Division